Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L7	9	I4 vehicle seat power adjust\$4 system (rollover or overturn or crash or collision)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2006/11/28 15:26
L5 _.	1	I4 vehicle seat (high same power) (motor same speed) power adjust\$4 system (rollover or overturn or crash or collision)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2006/11/28 15:24
L6	25	("2076828" "2209122" "2812044" "2993569" "3232124" "3243023" "3741513" "4177887" "4284935" "4706791" "5105924" "5545109" "5588517" "5896973" "6260685" "6273233" "6288464" "6412618").PN. OR ("6762579"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/11/28 15:05
S41	382	vehicle seat (high same power) (motor same speed) power adjust\$4 system (rollover or overturn or crash or collision)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2006/11/28 14:54
L4	725	(297/344.1).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/28 14:45
L3	563	(297/216.1).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/28 13:39
L2	120	(297/216.18).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/28 13:20

11/28/2006 4:14:38 PM Page 1

L1	27	("3452834" "4722550" "4900079"	US-PGPUB;	OR	ON	2006/11/28 13:02
	("4924162" "5130622" "5263765" "5320409" "5490706" "5536059" "5556160" "5567006" "5652704" "5707109"	USPAT; USOCR			١
		"5743591" "5927427" "5975508" "6024378" "6037731" "6056079" "6059253" "6088642" "6120082" "6122568" "6182783" "6193297"				
		"6691015").PN. OR ("7068178"). URPN.		:		
S44	8	vehicle seat (high with power) (motor with velocity) adjust\$4 (rollover or overturn)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2006/11/28 11:50
S43	. 1	vehicle seat (high with mode) (motor with speed) power adjust\$4 (rollover or overturn)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2006/11/28 11:50
S42	1	vehicle seat (high with mode) (motor with speed) power adjust\$4 system (rollover or overturn)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2006/11/28 11:49
S40	101	vehicle seat (high same power) (motor same speed) power adjust\$4 system (rollover or overturn)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2006/11/28 11:48
S39	3107	vehicle seat (high same power) (motor same speed) power adjust\$4 system	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2006/11/28 11:31
S38	9408	seat (high same power) (motor same speed) power adjust\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2006/11/28 11:30
S37	153	rollover sensor power seat low high mode operat\$3 adjust\$4 motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2006/11/28 11:27

Page 2 11/28/2006 4:14:38 PM C:\Documents and Settings\tabraham\My Documents\EAST\Workspaces\10,807,325 rollover- powr seat.wsp

S36	154	rollover sensor power seat low high mode operat\$3 adjustment	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2006/11/28 11:26
S31	210	rollover sensor vehicle seat low high operat\$3 adjustment	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2006/11/28 11:26
S35	13	("5261506" "5492368" "5564520" "5775726").PN. OR ("6182783"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/11/28 11:14
S34	90	(rollover with sensor) vehicle seat low high operat\$3 adjustment motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND .	ON	2006/11/28 10:27
S32	111	(rollover with sensor) vehicle seat low high operat\$3 adjustment	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON .	2006/11/28 10:27

11/28/2006 4:14:38 PM C:\Documents and Settings\tabraham\My Documents\EAST\Workspaces\10,807,325 rollover- powr seat.wsp Page 3

		r 	-	1	· · · · · · · · · · · · · · · · · · ·	
S33	88	("20010029438" "20010038202" "20010048215" "20020166710" "20020173882" "3719246" "3897846" "3899028" "4038876" "4470124" "4592565" "4691798" "5065612" "5115238" "5125472" "5172323" "5203600" "5218771" "5233213" "5261506" "5270959" "5337238" "5359515" "5363302" "5369580" "5375336" "5413378" "5451094" "5492368" "5508918" "5573269" "5590736" "5602734" "5610575" "5626359" "5646454" "5673932" "5684336" "5684701" "5699256" "5742916" "5755978" "5796002" "5825284" "5864768" "5890084" "5948027" "5948028" "5977653" "6002974" "6002975" "6036225" "6038495" "6047229" "6055472" "6065558" "6070681" "6076027" "6095554" "6104284" "6113138" "6141604" "6157295" "6169946" "6170594" "6178368" "6186539" "6192305" "6212455" "6225894" "6259982" "6262658" "6263261" "6264212" "6282474" "6292759" "6301536" "6315074" "6332104" "6341252" "6438463" "6477480" "6421592" "6438463" "6477480"	US-PGPUB; USPAT; USOCR	OR	ON	2006/11/28 10:05
					(
S19	677	power seat vehicle (compress or collapse) sensor adjustment	US-PGPUB; USPAT; USOCR	AND	ON	2006/11/28 09:52
S30	12	("2758872").URPN.	USPAT	OR	ON	2006/05/09 15:45

11/28/2006 4:14:38 PM C:\Documents and Settings\tabraham\My Documents\EAST\Workspaces\10,807,325 rollover- powr seat.wsp Page 4

520	83	("20010028186" "2193949"	LIS-DCDLIR.	OR	ON	2006/05/09 15:12
S29	83	("20010028186" "2193949" "2959446" "2965403" "3001815" "3732944" "3831997" "3848886" "3871470" "3897101" "3912295" "3961805" "3992046" "3998291" "4008909" "4152012" "4156472" "4317584" "4413856" "4458921" "4702515" "4832409" "4881781" "4901500" "5033593" "5040646" "5048888" "5123673" "5167421" "5201912" "5224574" "5244248"	US-PGPUB; USPAT; USOCR	OR	ON	2006/05/09 15:12
		"5286085" "5409262" "5429388" "5437494" "5552986" "5566777" "5626203" "5636424" "57864667" "5785347" "5794978"				
		"5810417" "5853195" "5876077" "5876078" "5911433" "5947543" "5984357" "5984402" "6003934" "6003937" "6042190" "6068329"				
	·	"6092853" "6116561" "6170865" "6179370" "6186574" "6193296" "6203098" "6224131" "6227563" "6227597" "6237991" "6241280" "6254164" "6299238" "6299239"				·
•		"6394535" "6398292" "6419271" "6422632").PN. OR ("6592166"). URPN.				
S28	1179	power seat vehicle lateral adjustment back slide	USPAT; USOCR	AND	ON	2006/05/09 11:39
S26	4771	power seat vehicle lateral adjustment	US-PGPUB; USPAT; USOCR	AND	ON	2006/05/09 11:38
S24	130	power seat vehicle lumbar sensor adjustment (weight or size)	US-PGPUB; USPAT; USOCR	AND	ON	2006/05/09 11:37
S25	10	("4797824" "5058852" "5170364" "5748473").PN. OR ("6055473"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/05/08 16:13
S20	556	power seat vehicle (compress or collapse) sensor adjustment (weight or size)	US-PGPUB; USPAT; USOCR	AND	ON	2006/05/08 15:14
S23	38	("2839124" "2919744" "3022681" "3125318" "3194530" "5014958").PN. OR ("5462337"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON `	2006/05/08 14:57

	<u> </u>					
S22	20	("3915493" "4836597" "4880199" "4927201" "4966045" "4971379" "5014958" "5348264" "5620225" "5696409" "5697662" "5730414" "5752845" "6050835").PN. OR ("6250703"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/05/08 14:51
S21	35	("3617021" "3951004" "4432583" "4645159" "4880199").PN. OR ("5014958").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/05/08 14:18
S18	1786	power seat vehicle (compress or collapse) sensor	US-PGPUB; USPAT; USOCR	AND	ON	2006/05/08 14:04 ·
S17	7182	power seat vehicle (compress or collapse)	US-PGPUB; USPAT; USOCR	AND	ON .	2006/05/08 13:59
S16	19	("3858930" "3899042" "4722550" "4884652").PN. OR ("5186494"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/05/08 13:57
S15	792	rollover sensor seat (slide or lateral or side)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND .	ON	2006/05/05 10:54
S1	8	("20020188393" "5492368" "607688 7" "6182783").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/05 10:52
S14	20	("3860923" "4673937" "5054810" "5174409" "5451094" "5558370" "5585798" "5748477" "5825098" "5927752" "6014601" "6123357" "6170862" "6186537" "6256565" "6278360").PN. OR ("6574540"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/05/04 09:59
S13	2	("6574540").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/05/04 09:58
S12	3	"10189403"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/04 09:58

					1	
S11	2	("20020188393").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/04 09:57
S10	0	("2002/0188393").URPN.	USPAT	OR	ON	2006/05/04 09:55
59	8	("4512604").PN. OR ("5407244"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/05/04 08:02
S8	144	S7 and vehicle and (lateral translation)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/03 17:34
S7	709	(297/344.1).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/05/03 17:33
S5	536	(297/216.1).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/05/03 17:32
S6	345	(297/217.3).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/05/03 17:09
S3	41	("3981518" "4154472" "4257626" "4738485" "4772046" "4917210" "4958854" "4999004" "5125472" "5149165" "5186494" "5211423" "5288105" "5290062").PN. OR ("5492368"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/05/03 17:09
S4	120	(297/216.18).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/05/03 15:39
S2		("2725921" "3578376" "3610679" "3731972" "3732944" "3957304" "3998291" "4008917" "4512604" "5203600" "5490706" "5564520" "5645316" "5697670" "5716102" "5743591" "5810417" "5823627" "5908219").PN. OR ("6076887"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/05/03 13:33